

1st International Conference on LWR Fuel Performance, Modelling and Experimental Support

September 14–19, 2025

Nessebar, Bulgaria




Westinghouse LTA inspection at Temelín NPP

Michal Kuna, Jan Höglund
Westinghouse Electric Sweden



Outline

- History
- Motivation
- Preparation
- Inspection
- Results



History

- Fuel inspection and repair from 2002 to 2009
- 61 rods removed from VV-6 (half leaking, half tight)
- Fuel Rod (FR) from Fuel Assembly (FA) BE24 broken in 2009
 - => FR manipulation stopped at Temelín
- In 2020 SIPS introduced at Temelín
 - Solely for visuals + geometry measurement
- Westinghouse FRIE (MSIO) still available at Temelín
 - Able to remove TN, FR and FR inspection
 - Highly modular

History



- In 2020 **SIPS** introduced at Temelín
 - Solely for visuals + geometry measurement
- Westinghouse **FRIE** (MSIO) still available at Temelín
 - Able to remove TN, FR and FR inspection
 - Highly modular
 - Some maintenance needed in 2024

Motivation for inspection

Pro&Cons

- **Leaking LTA after 3y of operation** – unknown reason, normal appearance
 - ČEZ sign a contract with WSE for region deliveries
 - Westinghouse support
 - FRIE maintenance and upgrade
 - Experienced staff to perform all manipulation
 - Emergency scenarios and countermeasures prepared
 - Good experience with inspections from Ukraine
-
- !! Perceived risks of pulling leaking FR due to historical experience
 - !! VVER-1000 SPF and water purification system aren't design for broken FR scenario
 - !! **Time during the outage** - FRIE takes longer to raise and tear down than SIPS
 - !! Any problem has huge impact on the outage

Framatome and Westinghouse to supply fuel to Temelín

13 April 2022



Westinghouse of the USA and Framatome of France have been awarded a long-term contract by Czech utility ČEZ for the supply of nuclear fuel assemblies to the Temelin nuclear power plant.



Temelin units 1 and 2 - both VVER-1000 reactors - have been in operation since 2000 and 2003, respectively (Image: ČEZ)

ČEZ said three bidders - Framatome, Westinghouse and Russia's TVEL - participated in the tender, which was launched in April 2020.

Decision to perform the inspection

On conditions:

- **Only tight FR**, 112 hours in the outage
- Contingency plans and equipment in place

Main inspection Goal:

- Assess **Grid To Rod Fretting (GTRF)** performance

Secondary inspection goal:

- Perform leak search of WTA2 with UT methods (AFIS)

Evolution: From VVANTAGE6 to RWFA-T

2000

2005


2012

2015


2019

2026


**Temelín
VV6 Phase 1X**




**SU3
LTA**



**SU3
(R)WFA**



Temelín LTA




RWFA-T



Preparations

FRIE upgrade & maintenance

- Eddy Current – measure defect volume
- Cameras – high res, color
- FR handling tool – smoother FR extraction
- UT probes – find leaking FR
- Seals, bearings, etc.. maintenance



Preparations (continued)



FOSAR & Fissile material container

FOSAR

- Can collect small debris like broken pellets, pieces of cladding or other
- Vacuum to filter or collect with tweezers


Fissile material container

- Designed per Temelín needs
- Intermediate storage of radioactive material, even pellets in SFP cell or plant hermetic seal container
- Storage of FOSAR filters
- Remote, robust handling in SFP sections under water

Emergency procedures

- For collecting and handling broken FR, loose pellets and other debris
- Handling heavily contaminated water
- Emergency cooling of pool section with FRIE

Preparations (continued)



FOSAR & Fissile material container

FOSAR

- Can collect small debris like broken pellets, pieces of cladding or other
- Vacuum to filter or collect with tweezers

Fissile material container

- Designed per Temelín needs
- Intermediate storage of radioactive material, even pellets in SFP cell or plant hermetic seal container
- Storage of FOSAR filters
- Remote, robust handling in SFP sections under water

Emergency procedures

- For collecting and handling broken FR, loose pellets and other debris
- Handling heavily contaminated water
- Emergency cooling of pool section with FRIE

Inspection

Westinghouse Field Acceptance Criteria

The design is accepted in the aspect of GTRF if both bullets below are met

- ✓ Less than 44% through wall on a single individual wear depth
- ✓ Less than 10% through wall from all measurements on 95/95 basis.

Work Scope

- Removal of Top Nozzle on the assembly to be inspected
- Visual inspection of individual fuel rods
- Eddy Current (EC) measurements on the individual fuel rods to obtain wear data
- Fuel rods are put back in the assembly
- Top Nozzle is re-installed on the inspected assembly

Program

- Given boundary condition – can't find the root cause of leaking FR =>
 - ✓ Only UT leak search with the AFIS system on WTA2
- Focus on GTRF =>
 - ✓ Inspection of identical, leak-free WTA3
 - ✓ 40 FRs extracted, inspected and measured with EC
 - ✓ Rods were chosen based on VIPER long term wear test results

Inspection

Westinghouse Field Acceptance Criteria

The design is accepted in the aspect of GTRF if both bullets below are met

- ✓ Less than 44% through wall on a single individual wear depth
- ✓ Less than 10% through wall from all measurements on 95/95 basis.

Work Scope

- Removal of Top Nozzle on the assembly to be inspected
- Visual inspection of individual fuel rods
- Eddy Current (EC) measurements on the individual fuel rods to obtain wear data
- Fuel rods are put back in the assembly
- Top Nozzle is re-installed on the inspected assembly

Program


- Given boundary condition – can't find the root cause of leaking FR =>
 - ✓ Only UT leak search with the AFIS system on WTA2
- Focus on GTRF =>
 - ✓ Inspection of identical, leak-free WTA3
 - ✓ 40 FRs extracted, inspected and measured with EC
 - ✓ Rods were chosen based on VIPER long term wear test results

Inspection

Westinghouse Acceptance

The design is accepted if
GTRF if both bullets belong



- ✓ Less than 44% thru
individual wear dep
- ✓ Less than 10% thru
measurements on 1



Program

- Given boundary condition – can't find the root cause of leaking FR =>
 - ✓ Only UT leakers search with the AFIS system on WTA2
- Focus on GTRF =>
 - ✓ Inspection of identical, leak-free WTA3
 - ✓ 40 FRs extracted, inspected and measured with EC
 - ✓ Rods were chosen based on VIPER long term wear test results

Inspection



✓ Rods were chosen based on VIPER test results

RESULTS

- **Visual Inspections:**

- 40 rods, 13 grids, 1+2 spring/dimples per cell → **1560 contact positions** inspected
- **No fretting wear observed.** Only normal contact marks


- **EC-testing**

- **No detectable mark on any rod**
- See Table to the right: Code NDD = Not Detectible Defect

**GTRF Acceptance Criteria
are Fulfilled for RWFA-T**

| LINE | ASSY | ROD | ROD | VOLTS | DEG | CODE | % | CH | LOCATION | ACQ | EXTENT |
|------|------|-----|-----|-------|-----------|--------|---|----|----------|----------|---------|
| 1 | | | | | CAL | 3 | | | TEM | ACQ | |
| 2 | | | | | COMP | TEMLIN | | | | | |
| 3 | | | | | PROBE | .360 | | | | | |
| 4 | | | | | ANALYST | 10289 | | | II | 04/20/24 | |
| 5 | | | | | OPERATOR | 10289 | | | II | | |
| 6 | | | | | ACQ START | 1959 | | | | 04/19/24 | |
| 7 | | | | | | | | | | | |
| 8 | WTA3 | A | 11 | | | NDD | | | | | SPR TIP |
| 9 | WTA3 | J | 14 | | | NDD | | | | | SPR TIP |
| 10 | WTA3 | U | 14 | | | NDD | | | | | SPR TIP |
| 11 | WTA3 | C | 13 | | | NDD | | | | | SPR TIP |
| 12 | WTA3 | U | 21 | | | NDD | | | | | SPR TIP |
| 13 | WTA3 | U | 12 | | | NDD | | | | | SPR TIP |
| 14 | WTA3 | U | 15 | | | NDD | | | | | SPR TIP |
| 15 | WTA3 | T | 13 | | | NDD | | | | | SPR TIP |
| 16 | WTA3 | T | 16 | | | NDD | | | | | SPR TIP |
| 17 | WTA3 | G | 1 | | | NDD | | | | | SPR TIP |
| 18 | WTA3 | F | 5 | | | NDD | | | | | SPR TIP |
| 19 | WTA3 | B | 1 | | | NDD | | | | | SPR TIP |
| 20 | WTA3 | K | 1 | | | NDD | | | | | SPR TIP |
| 21 | WTA3 | M | 12 | | | NDD | | | | | SPR TIP |
| 22 | WTA3 | U | 19 | | | NDD | | | | | SPR TIP |
| 23 | WTA3 | H | 18 | | | NDD | | | | | SPR TIP |
| 24 | WTA3 | A | 9 | | | NDD | | | | | SPR TIP |
| 25 | WTA3 | C | 10 | | | NDD | | | | | SPR TIP |
| 26 | WTA3 | C | 7 | | | NDD | | | | | SPR TIP |
| 27 | WTA3 | G | 9 | | | NDD | | | | | SPR TIP |
| 28 | WTA3 | K | 15 | | | NDD | | | | | SPR TIP |
| 29 | WTA3 | K | 21 | | | NDD | | | | | SPR TIP |
| 30 | WTA3 | Q | 21 | | | NDD | | | | | SPR TIP |
| 31 | WTA3 | P | 19 | | | NDD | | | | | SPR TIP |
| 32 | WTA3 | N | 7 | | | NDD | | | | | SPR TIP |
| 33 | WTA3 | M | 5 | | | NDD | | | | | SPR TIP |
| 34 | WTA3 | T | 10 | | | NDD | | | | | SPR TIP |
| 35 | WTA3 | L | 2 | | | NDD | | | | | SPR TIP |
| 36 | WTA3 | L | 8 | | | NDD | | | | | SPR TIP |
| 37 | WTA3 | N | 6 | | | NDD | | | | | SPR TIP |
| 38 | WTA3 | U | 11 | | | NDD | | | | | SPR TIP |
| 39 | WTA3 | N | 20 | | | NDD | | | | | SPR TIP |
| 40 | WTA3 | Q | 20 | | | NDD | | | | | SPR TIP |
| 41 | WTA3 | K | 20 | | | NDD | | | | | SPR TIP |
| 42 | WTA3 | A | 8 | | | NDD | | | | | SPR TIP |
| 43 | WTA3 | D | 5 | | | NDD | | | | | SPR TIP |
| 44 | WTA3 | A | 1 | | | NDD | | | | | SPR TIP |
| 45 | WTA3 | N | 11 | | | NDD | | | | | SPR TIP |
| 46 | WTA3 | M | 6 | | | NDD | | | | | SPR TIP |
| 47 | WTA3 | R | 21 | | | NDD | | | | | SPR TIP |

Number of contact points per rod





Contact mark and scratch from rod extraction, rod G09



Contact mark on rod U11




Typical contact marks on rod A01



Typical contact marks on rod A01

AFIS Inspection on the Leaking WTA2

- Rod C4 detected as leaking
- No excessive growth
- Difficult to visually inspect in third row



SUMMARY

Safe rod extraction and re-insertion within given time in VVER-1000 conditions.

WTA2 - leaking

- One leaking FR identified
- No excessive growth observed
- Root cause not established

WTA3 – not leaking

- Thoroughly examined for GTRF
- 1560 contact points investigated
- **No fretting wear** observed visually
- No detectable marks on EC

Overall performance

- No broken fuel rod
- Finished about 20 hours sooner
- No other major problem
- Operational „issues“ (UT probe replacement, hosing replacement, etc...)
- Foreign material from pools caused delays



Questions?



Thank you